

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd. Wood Village, OR 97060 (503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description						
2008 Chevrole	t Impala V6 4D	Sedan LS				
VIN	2G1WB58K	2G1WB58K381262305				
Ext. Color	Red					
Int. Color	Black	Interior Cloth				
Mileage	31,603 Actu	31,603 Actual Miles				
Engine	3.5L 6-Cylin	3.5L 6-Cylinder Gas				
Transmission	Automatic	Automatic				



	Auction Data		Declarations		
Sale Date	To Be Announced	Warranty	GSA Regular Terms		
Run#	To Be Announced Inv # 2477	Mileage	31,603 Actual Miles		
Consignor	GSA FLEET SERVICES	Title	Clear Title		

Equipment

- Front Wheel Drive
- Air Conditioning
- Power Locks
- · Anti Lock Brakes
- Keyless Entry
- Power Brakes

- Automatic Transmission
- Power Trunk
- Trip Counter
- Steel Wheels
- Hard Top
- Electric Mirrors

- · 6 Cylinder Gas
- Electronic Traction Control
- Cruise Control
- · Tilt Steering Wheel
- Rear Defog

- 5 Passenger
- · Power Windows
- Dual Air Bag
- AM/FM CD
- · Power Steering

		Damage Descriptions (CR completed on 4/22/2015 by NATE HALL)								
	#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front										
	1	Front Bumper	Chips	Multiple Instances						
	2	Hood	Chips	Multiple Instances						
				Front Subtotal	-	-				

2008 Chevrolet Impala V6 4D Sedan LS

VIN: 2G1WB58K381262305

Inv#: 2477

	#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Interior										
	3	Carpets	Dirty	Multiple Instances						
	4	Headlining	Dirty	Multiple Instances						
	5	Interior	Dirty	Multiple Instances						
	6	Seats	Dirty	Multiple Instances						
				Interior Subtotal		-	-	-	-	-
Left										
	7	Left Front Door	Previous Repair	None						
	8	Left Front Fender	Previous Repair	None						-
	9	Left Qtr Panel	Scratched	Multiple Instances						-
	10	Left Rear Door	Scratched	Multiple Instances						
	11	Left Rear Door	Previous Repair	None						<u>-</u>
										
				Left Subtotal		-				
Mechar	nica	al								
moona		Engine	Checked - Ok	None						
	13	Transmission	Checked - Ok	None						
				Mechanical Subtotal						-
Rear										
	14	Deck Lid	Scratched	Multiple Instances						
	15	Rear Bumper	Scratched	Multiple Instances						

2008 Chevrolet Impala V6 4D Sedan LS

		Rear Subtotal		 	 	
Right						
16 Right Rear Door	Scratched	Multiple Instances				
		Right Subtotal		 -	 	
				-	 	
Structural						
17 Frame	Checked - Ok	None				
		Structural Subtotal		 	 	
		Total	-	 	 	
				-	 	

Tires				
Region	Brand	Size	Tread Depth	
Left Front	FIRESTONE	/-	Average (Average)	
Left Rear	FIRESTONE	/-	Average (Average)	
Right Front	FIRESTONE	/-	Average (Average)	
Right Rear	FIRESTONE	/-	Average (Average)	
Spare	FACTORY	/-	Average (Average)	

Miscellaneous					
Coolant level	OK				
Interior odor	OK				
Oil level	OK				
Transmission fluid level	OK				

Images



2008 Chevrolet Impala V6 4D Sedan LS

